



Residential Leak Detection Case Study

Rutland Farm
Stone House
LE15 9AZ



Leak on Metered Potable Water Supply

Customer's property is supplied by a blue 25mm blue HDPE Pipe, the meter is located at the farm gate property boundary. The water meter continues to spin when no water is consumed/used. The leak had been on-going for 18months.

The Tricky bit

The distance from water meter to the farm house was 1.5km and the pipe route is unknown. The pipe travels through a concrete bridge over a railway and under a small brook.

Insurance Company Solution

The customer had 'trace & access cover to the value of £5,000'. The insurance company sent out 3 different companies over a 4 month period that were all unable to locate the pipe or the leak. These companies spent the £5000 cover.

The customer contacted Leakbusters Limited directly and paid for the survey themselves.

We located the leak accurately. The customer was charged £500 + materials/vat

'Leakbusters turned up on time and did exactly what they promised'
Customer